

Ref. No. Docket PL-030473

CERTIFIED MAIL

June 12, 2003

Chris Hoidal
Director - Western Region
Office of Pipeline Safety
12600 West Colfax Ave, Suite A-250
Lakewood, Colorado 80215-3736

Dear Mr. Hoidal:

Subject: Standard Inspection Report for Exxon Mobil Spokane Terminal

The Washington Utilities and Transportation Commission (WUTC) has completed a standard inspection (Docket number PL-030473) of Exxon Mobil Spokane Terminal. A review of operation and maintenance manuals was conducted before the field facility inspection. The field inspection included a records review, inspection of six breakout tanks, and the piping from the Yellowstone pipeline manifold to the tanks. The piping inspection included pipe, valves, fittings, pipe casings through the dike, and pipe supports.

This terminal facility was inspected two years ago by WUTC and some violations were found during the field inspection. The operator corrected the deficiencies promptly and the condition of the piping and tanks appeared to have improved noticeably since the last inspection.

Office of Pipeline Safety-Exxon Mobil Spokane Terminal
Docket PL-030473
June 12, 2003
Page 2

The 2003 inspection did not find any probable violation. The reports enclosed are:

- IOCS Data Form
- Breakout Tank Inspection Form

The post inspection memo, dated April 22, 2003, was sent to the Western Region office via e-mail on May 7, 2003.

If you have any questions, please contact me at (360) 664-1115 or Kuang Chu, Pipeline Safety Engineer, at (360) 664-1182.

Thank you.

Sincerely,

Steve King
Acting Pipeline Safety Director

Enclosures